


FIG.1



EXAMPLES OF PDL COMMAND

- CIRCLE / COLOR = GRAY / SIZE = 100 / POSITION = x ; 20, y ; 40
- RECTANGLE / COLOR = WHITE / SIZE = 40x30 / POSITION = x ; 25, y ; 45
- CHARACTER / CHARACTER LINE "ABC" / SIZE = 15
POINT / COLOR = BLACK / POSITION = x ; 50, y ; 50
- IMAGE / SIZE = 50x30 / POSITION = x ; 30, y ; 5 / IMAGE
DATA = FFA032D0 . . . 807236CAB0680EF5 /




FIG.2




FIG.3




FIG.4




FIG.5




FIG. 6




FIG.7A




FIG.7B




FIG.7C




FIG.8




FIG.9A




FIG.9B



FIG.9C




FIG.10




FIG.11




FIG.12




FIG.13




FIG.14A

No. 1			
DOCUMENT NAME	STATUS	OWNER	SITUATION
A	PRINTING	B	***

FIG.14B

20/20




FIG.14C